Follow-up Service Inspection Report E2253501240611142321



INSPECTION DETAILS			
Date:	2024-06-11	File Number.:	E225350
Responsible Office:	Melville	Volume:	1
Inspection Center:	221	CCN:	QMMY2
Product Type:	Fabricated Parts	UL Rep Name:	Isaac Curtis
Deliverable Type:	Recognized	UL Rep ID:	32476
Party Site Number:	603704	Subscriber Factory No.:	332093-001
Manufacturer Name:	TSP INC	Factory Rep Name:	Ms. Lori Tigert
Manufacturer Address:	2009 Glenn Pkwy	Factory Rep Phone:	1-513-732-8900, 108
	Batavia, OH 45103-1676	Factory Rep Email:	ltigert@tspinc.com
Applicant:	TSP INC (603704)		
	2009 Glenn Pkwy		
	Batavia, OH 45103-1676 US		
Nature of visit:	Regular Inspection	Sample Status:	Samples not required
UL Marks Used?	Yes	UL Marks Removed?	No
Variation Notice Issued?	No	Specific Environmental	No
		Conditions Required?	

PRODUCT DOCUMENTS/PRODUCTION READY VISIT				
Model	Product	Section	Multiple Listed	
0.060 Lexan 8010SG (lot# 243004)	Fabricated Parts		No	
0.177 Lexan 9034 (lot# 241704)	Fabricated Parts		No	

UL-OWNED EQUIPMENT CALIBRATION

No UL owned inspection, measuring and test equipment used during inspection.

COMMENTS	
Additional Comments	Plastics Traceability Program
Comments After Submission:	

In addition to the requirements specified in the applicable UL Services agreement and Follow-Up Service Procedure, UL further defines responsibilities, duties and requirements for both manufacturers and UL representatives in the document titled "UL Mark Surveillance Requirements" that can be located at <u>www.ul.com/fus</u>, and in accordance with the applicable terms and conditions of the document at <u>www.ul.com/responsibilities</u>. Manufacturers without Internet access may obtain the current versions of these documents from their local UL customer service representative or UL field representative. The Field Engineer is completing the inspections per Internal Procedure UL Mark Surveillance Program Policy Manual -ULID-004573.