



Follow-up Service Inspection Report E2253501241112200611

INSPECTION DETAILS			
Date:	2024-11-12	File Number.:	E225350
Responsible Office:	Melville	Volume:	1
Inspection Center:	221	CCN:	QMMY2
Product Type:	Fabricated Parts	UL Rep Name:	Logan LaChapelle
Deliverable Type:	Recognized	UL Rep ID:	19376
Party Site Number:	603704	Subscriber Factory No.:	332093-001
Manufacturer Name:	TSP INC	Factory Rep Name:	Ms. Lori Tigert
Manufacturer Address:	2009 Glenn Pkwy Batavia, OH 45103-1676	Factory Rep Phone:	1-513-732-8900, 108
		Factory Rep Email:	ltigert@tspinc.com
Applicant:	TSP INC (603704) 2009 Glenn Pkwy Batavia, OH 45103-1676 US		
Nature of visit:	Regular Inspection	Sample Status:	Samples not required
UL Marks Used?	Yes	UL Marks Removed?	No
Variation Notice Issued?	No	Specific Environmental Conditions Required?	No

PRODUCT DOCUMENTS/PRODUCTION READY VISIT			
Model	Product	Section	Multiple Listed
Lexan 8010SG (work order #18589)	Fabricated part		No

UL-OWNED EQUIPMENT CALIBRATION
No UL owned inspection, measuring and test equipment used during inspection.

COMMENTS	
Additional Comments	
Comments After Submission:	

In addition to the requirements specified in the applicable UL Services agreement and Follow-Up Service Procedure, UL further defines responsibilities, duties and requirements for both manufacturers and UL representatives in the document titled "UL Mark Surveillance Requirements" that can be located at www.ul.com/fus, and in accordance with the applicable terms and conditions of the document at www.ul.com/responsibilities. Manufacturers without Internet access may obtain the current versions of these documents from their local UL customer service representative or UL field representative. The Field Engineer is completing the inspections per Internal Procedure UL Mark Surveillance Program Policy Manual -ULID-004573.